




## 0,5 L 1,5L 2,5L









#### PREPARATION

 Bh
 24h

 Recoat
 Fully dry

DRYING TIME









# PREPARATION of the surface is ESSENTIAL. All surfaces must be clean, dry and free of grease.G r e ase or plastic-coated materials can affect adhesion of the paint.

BARE OR NEW SURFACE:

WOOD: Sand lightly and remove dust. Degrease exotic woods with denatured alcohol.

IRON: Degrease new metal with denatured alcohol. For rusted metal, remove rust with a metal brush and then remove dust.

PVC-ALUMINIUM-ZINC-STEEL-COPPER: Sand lightly with a 150 grit sandpaper. The surface must then be thoroughly washed with a soda-based (alkaline) cleaner and rinsed well. Non-ferrous m e tals: Lightly sand the surface. PAINTED, STAINED OR VARNISHED SURFACE IN GOOD CONDITION:

WOOD-IRON: Sand lightly with a fine grit sandpaper (120) and remove dust. PVC-ALUMINIUM-ZINC-STEEL-COPPER: Sand lightly with a 150 grit sandpaper. The surface must t h e n be thoroughly washed with a soda-based (alkaline) cleaner and rinsed well.

PAINTED, STAINED OR VARNISHED SURFACE IN POOR CONDITION: WOOD: Scrape away any flaking material, sand and remove dust. IRON: Brush away any rust and scrape off any remaining paint, then degrease

with denatured alcohol. PVC-ALUMINIUM-ZINC-STEEL-COPPER: Sand lightly with a 150 grit sandpaper. The surface must t h e n be thoroughly washed with a soda-based (alkaline) cleaner and rinsed well.

### PERFORMANCE

- Shock, stains, UV and weather resistant
- 7 year guarantee

The seven year guarantee applies when product is applied according to preparation and application instructions. Exposition: Only vertical surfaces. The guarantee can be reduced on surfaces in high moisture areas and does not apply on stagnant water surfaces. The guarantee is limited to refunding of the product (presentation of the r e c eipt and the tin) and concerns only the aspect of the paint.

### APPLICATION

Stir the paint thoroughly before and during application, working around the bottom of the tin to mix properly. Ready-to-use product, do not dilute. 1. Start by painting the angles, corners and grooves of the surface to be painted.

2. Continue with regular cross strokes to avoid excessive build-up.

3. Leave to dry for around 8 hours. Sand lightly and remove dust. Apply the second coat of paint in the same way.

4. L eave to dry for 24 hours before use.

For bright colours, an additional coat may be necessary. Optimum performance and resistance is obtained after 2 weeks of drying.



