

RENOVATION IT'S EASY



1. SURFACE PREPARATION

Preparation is an essential step. Be sure to clean all your surfaces with a soda based cleaner (alkaline) like sugar soap and rinse well.

2. PAINT APPLICATION

- Apply the paint in 2 coats to guarantee performance and strength. Use a roller suitable for painting. The quality of the tools used will affect the final result.
- See instructions on the pack for drying times between each coat and following final application.
- Painting must be carried out at room temperature, between 12°C and 25°C (to avoid any risk of separation, peeling or blisters).
- Optimum performance and strength of these paints is reached after 20 days. Treat the surface with care immediately after painting.
- For everyday care, clean painted surfaces with a non-abrasive sponge and mild detergent.
- Refer to any special instructions for your paint on the back of the pack.